

User DVD Calibration Files

A folder named “Calibration Files” is found on the User Software CD/DVD. It contains files designed to support professional printing workflows, like those driven by Hot Folders, or requiring non-standard settings. These files can be printed in place of the pages normally emitted by ColorWise Pro Tools Calibrator. These printed pages are meant to be measured by ColorWise Pro Tools Calibrator.

In this folder, you can find these two folders:

PS Files:

PostScript files that you can download to the Fiery from Command WorkStation (CWS), in order to calibrate or verify the printer calibration.

Halftone Calibration Files:

Contains files in image (Photoshop PSD) and in graphics (EPS) formats. These files are not meant to be downloaded directly, but to be imported into professional desktop publishing applications, in order to create your custom calibration pages. These pages can be created on custom paper sizes and printed with the full control provided by CWS. You can, for instance, use a halftone other than your Fiery factory default, or halftones produced using the optional Fiery Graphic Arts feature “Halftone Simulation”. Be careful not to color manage these files. Do not embed color profiles, scale or modify the color values.

For calibration, you must print the Halftone Calibration Files using CMYK Simulation set to ColorWise OFF. For verification, print them using CMYK Simulation set to None.

TIP: if you download these files to the Fiery Hold Queue, you can reprint them on demand from this location.